


### Aligning the Hood by Russ Furstnow

After completing the restoration of a 1921 touring, we noticed the hood did not align up very well with the



The solution proved to be fairly easy. The body was raised in relation to the height of the radiator, and the

When everything was tightened down, the hood fit perfectly and no longer rubbed the paint from the radiator.